

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20160119-E224162  
**Report Reference** E224162-20030924  
**Issue Date** 2016-JANUARY-19

**Issued to:**

ROCKWELL AUTOMATION/ ALLEN-BRADLEY  
1201 S 2nd St  
Milwaukee, WI 53204-2410

**This is to certify that  
representative samples of**

CIRCUIT BREAKER AND GROUND-FAULT CIRCUIT  
INTERRUPTERS

**Evaluated to UL 489**

1492-MCGAT115, 1492-MCGAT120, 1492-MCGAT125,  
1492-MCGAT130, 1492-MCGAT140

**Evaluated to UL 489 and UL 943**

1492-MCGAT215, 1492-MCGAT220, 1492-MCGAT225,  
1492-MCGAT230, 1492-MCGAT240, 1492-MCGAT250

Have been investigated by UL in accordance with the  
Standard(s) indicated on this Certificate.

**Standard(s) for Safety:**


UL 489, Molded-Case Circuit Breakers, Molded-Case  
Switches and Circuit-Breaker Enclosures  
UL 943, Ground-Fault Circuit-Interrupters

**Additional Information:**

See the UL Online Certifications Directory at  
[www.ul.com/database](http://www.ul.com/database) for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's  
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please  
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

